

Brison R/C Engines

REPAIR POLICY

BRISON factory authorized warranty and repair service is performed exclusively by:

BJ's MODEL ENGINE SERVICE

Attn: Bill Jensen

51 Hillside Dr.

Beacon Falls, CT 06403

Phone and Fax: 203-888-4819

Email: wbilljensen@cs.com

Web: www.bj-model-engines.com

Please contact BJ's for all repairs, warranty and non-warranty.

Standard repair info:

Estimates: For common repairs, you may do your own estimate on-line at www.bj-model-engines.com; or, email, phone, or fax for a prompt free estimate.

Quotes: Accurate, detailed, diagnosis and repair quote with disassembly as required; included with repair, \$30 minimum without repair plus return S&H. Twins may be higher.

Payment options: Major credit cards, PayPal, check, Money Order.

General: Minimum charge for repairs and quotes: \$30. Typical repair labor charge \$25/hr. Payment required before return shipping. Allow about 10 workdays in our shop for most repairs. Please include muffler, prop nut and washer. No need to send the prop, but, specify prop size and type if you have a favorite,

Return packing and shipping: \$18 for singles, \$24 for twins.

For reference: Besides Brison, we do accept for repair, the following Sachs/Dolmar style engines:

1. Walker Machine Engines

2. A&M Aircraft Engines (Except Twins)

WE DO NOT WORK ON “CHOP OUTS”, WEED EATER CONVERSIONS, OR BYRON CONVERSION TYPE ENGINES. WE DO NOT MODIFY ENGINES OR DO CUSTOM EXHAUST.

Please see “Shipping Instructions” for shipping engines to us.